

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1478
East
> 1
1.870 mi.
9874 ft.

**BASEMENT FLOOD AT 157 IRWIN ST
157 IRWIN STREET (FLOOD SOURCE)
BROOKLYN, NY**

**NY Spills S112810001
N/A**

**Relative:
Higher**

**Actual:
4 ft.**

SPILLS:

Name: BASEMENT FLOOD AT 157 IRWIN ST
Address: 157 IRWIN STREET (FLOOD SOURCE)
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1215551 / 2013-02-25
Facility ID: 1215551
Facility Type: ER
DER Facility ID: 434141
Site ID: 478861
DEC Region: 2

Spill Cause: Storm
Spill Class: D3
SWIS: 2401
Spill Date: 2013-02-10
Investigator: JBOUGHT
Referred To: Not reported
Reported to Dept: 2013-02-13
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-02-13
Spill Record Last Update: 2013-02-25
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ELLIOT ROSS OR BONNIE SOMMER
DEC Memo: "2/25/13-Vought-Received call from Eilene Glassman (Ph:212-645-7046 cell:917-648-8518) and Eilene resides at she is next door neighbor of concerned location. There house was flooded with Hurricane and she saw insurance on 1/25 for neighbor and she asked him to make sure neighbors water was shut off as it was getting cold. Basement of 157 Irwin Street was flooded from water pipe again after Sandy. Basement was flooding from 2/4-2/10 and FNDY entered home and they could not enter basement as basement was flooded. DEP arrived onsite and shut down water and water was most likely seeping into Glassman's basement (161 Irwin Street) and she hired contractor to pump out her basement which most likely emptied basement of 157 Irwin as well as per NYCDEP. Glassmans basement was flooded from seepage from 157 Irwin Street. No oil was observed in 161 Irwin as per Glassman and her concerns were about house security as well as oil tank submerged. No reports of oil vapors from 161 Irwin as per Glassman and she also noted that basement was flooded so heavily by water leak that water came out of basement and ran down sewers (which most likely flushed out all product) IF there was a second spill event after Sandy. Glassman also expressed concerns with gas main as 157 Irwin was not secure (no door locks) and Vought suggested she call National Grid.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

Glassman noted that she and many neighbors were actively calling various utilities and public representatives due to home and that homeowner of 157 Irwin was elderly man who had not been home since prior to Hurricane Sandy on 10/18/12. Vought also noted to Glassman that second basement flood from water line did not rise above vent line and therefore most likely did not affect oil (if any in tank after Hurricane Sandy). Vought requested to Glassman to call DEC if there was every any evidence of an oil spill and also informed her that DEC would be closing this case due to the information she provided. Spill transferred to Vought and then closed by Vought as no suggestion or evidence of spill."

"caller has reported that there is a flood in the basement of the house at above location - flooded into her house - reporting to be a fuel tank still in there full of #2 fuel - unsure of stability of tank - owner of property has New Jersey phone number - no cleanup being reported - would like to possibly have tank pumped out because of possible damage"

All Materials:

Site ID: 478861
Operable Unit ID: 1228619
Operable Unit: 01
Material ID: 2226291
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: Not reported
Oxygenate: Not reported